



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3007696

TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

s4 7-23-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	7/28/17
Target Finish:	7/28/17
Actual Start:	7/23/17
Actual Finish:	7/23/17
Report Date:	7/21/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007696 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
s4 7-23-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			SSELL				10		N		08:00	00:00	212.00
AREPAIR			ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007696 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
s4 7-23-17 No new defects noted in area.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Cumden To Linthicum

[illegible][illegible]

Reason for Inspection _____

7/24/17
Date

7/24



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3006383

TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
s1 7-24-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	7/23/17
Target Finish:	7/23/17
Actual Start:	7/24/17
Actual Finish:	7/24/17
Report Date:	7/20/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3006383 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
s1 7-24-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			SSELL				10		N		08:00	00:00	212.00
AREPAIR			ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3006383 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
s1 7-24-17 No new defects noted in area.

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Hunt Valley To Leather Vile

[illegible][illegible]

Reason for Inspection _____

7/25/17
Date

Daily Track Inspection

Inspection From LUTHERVILLE To COLD SPRING

[illegible][illegible]

Reason for Inspection _____

7/26/17
Date

7/25



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008921 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
07-25-2017

No new defects noted in area

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:				

Mileage Meter:	
Sched Start:	
Sched Finish:	
Target Start:	7/26/17
Target Finish:	7/26/17
Actual Start:	7/25/17
Actual Finish:	7/25/17
Report Date:	7/22/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48476

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008921 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
07-25-2017

No new defects noted in area

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008921 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
07-25-2017

No new defects noted in area

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		MPOLLAF						N		08:00	00:00	210.32
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		TSCHISLI						N		08:00	00:00	210.32
Total Actual Labor:													630.96



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008921 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
07-25-2017

No new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From LUTHERVILLE To COLD SPRING

[illegible][illegible]

Reason for Inspection _____

7/26/17
Date

7/25



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3008943

TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	7/26/17
Target Finish:	7/26/17
Actual Start:	7/25/17
Actual Finish:	7/25/17
Report Date:	7/22/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008943 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			SSELL				10		N		08:00	00:00	212.00
AREPAIR			ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008943 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Cold Spring To Camden - Penn

[illegible][illegible]

Reason for Inspection _____

Jane Pearson
Supervisory Certification

7/26/17
Date

7/25



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3008943

TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:				
Sched Start:		Mileage Meter:		
Sched Finish:	Site: LTRAIL			
Target Start:	Priority: 1			
Target Finish:	Work Type: PM			
Actual Start:	Status: CLOSE			
Actual Finish:	Parent:			
Report Date:	Person Group: MTA527			
Reported By: MTACRON	GL Account: J05-####-05270-#####-0901-#####-#####-####-#####-000-30-00			
Requestor of Work:	Warranty Situation Present? N			
	PM Num: 48477			
	Job Plan: 2956			
	Job Desc: TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S			
	Supervisor:			
	Lead: JREAVES3			
	Owner:			
	Owner Group:			
	Service:			
	Service Group:			
	Classification: 2732			
	Part Failure:			

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008943 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		SSELL				10		N		08:00	00:00	212.00
	AREPAIR		ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3008943 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 7-25-17 No new defects noted in area.

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Cold Spring To Camden - Penn

[illegible][illegible]

Reason for Inspection _____

7/26/17
Date

Light Rail MOW

Daily Track Inspection

Name T SCHISLER M POUARD Date 7-26-17 Page 1 of 1

Watchman G LAY WO# 3008995

Inspection From LINTHICUM To _____

Items	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	294+70 ^s		2	BOTH		W301	329	Y		
2.	118+90 ^s		6' AREA			M309	303	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items

Comments

1	SOUTH END OF BRIDGE OVER ROUTE 648, ANNAPOLIS RD
2	LID BROKEN OFF BOX IN 6' AREA JUST SOUTH OF CHAL LOWERY X-ING

Were switches in area inspected? YES X NO _____

Is this a Special Inspection? YES _____ NO X

Reason for Inspection _____

T Schisler
Track Inspectors Signature

Janna Pauer
Supervisory Certification

7/27/17
Date



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007689 TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
 1) Trk - 0 CM 862+50 LRV wheels breaking concrete out of flangeway of track .
 2) Trk -0 CM 848+00 Fouled ballast in three cribs and the ties in area are pumping.
 3) SW - 837 4 loose bolts in the frog .
 Track inspection complete.

Alias:	Location:	CHAIN_MARKER	Status:
Asset:	Year:	LT Rail Chain Markers	Type:
Serial Number:	Manufacturer:		
Office Address:	License:		
1155 344 West North Ave, Baltimore MD			

...sters:	Description	Unit of Measure	Last Reading Date	Last Reading
-----------	-------------	-----------------	-------------------	--------------

CI:	
Sched Start:	
Sched Finish:	
Target Start:	7/27/17
Target Finish:	7/27/17
Actual Start:	7/27/17
Actual Finish:	7/27/17
Report Date:	7/21/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48474

Job Plan:	2953
Job Desc:	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007689

TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N

1) Trk - 0 CM 862+50 LRV wheels breaking concrete out of flangeway of track .

2) Trk -0 CM 848+00 Fouled ballast in three cribs and the ties in area are pumping.

3) SW - 837 4 loose bolts in the frog .

Track inspection complete.

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N		



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007689

TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N

1) Trk - 0 CM 862+50 LRV wheels breaking concrete out of flangeway of track .

2) Trk -0 CM 848+00 Fouled ballast in three cribs and the ties in area are pumping.

3) SW - 837 4 loose bolts in the frog .

Track inspection complete.

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
20 AREPAIR			GLAM				10		N		08:00	00:00	210.32
20 AREPAIR			MPOLLAF				10		N		08:00	00:00	210.32
Total Actual Labor:													420.64



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007689

TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N

- 1) Trk - 0 CM 862+50 LRV wheels breaking concrete out of flangeway of track .
- 2) Trk -0 CM 848+00 Fouled ballast in three cribs and the ties in area are pumping.
- 3) SW - 837 4 loose bolts in the frog .

Track inspection complete.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Pollard Date 7-27-2017 Page 1 of 1
 Watchman Lam WO# 3007689
 Inspection From Hunt Valley To Lutherville

Items	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	862+00		0			M305	301	Y	N	
2.	848+50		0			M307	314	Y	N	
3.					837	S305	322	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items

Comments

1	LRV wheels breaking concrete of Flange way 15'
2	Fouled ballast 3 cribs 4 ties pumping
3	4 Loose bolts in the Frog
	Track inspection complete

Were switches in area inspected? YES ☒ NO ☐

Is this a Special Inspection? YES ☐ NO ☒

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

7/28/17
Date

7/27



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3007703

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

s2 7-27-17 Riding inspection due to manpower shortage. No new defects noted in area.

Alias:		Location:	CHAIN_MARKER LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	7/27/17
Target Finish:	7/27/17
Actual Start:	7/27/17
Actual Finish:	7/27/17
Report Date:	7/21/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-#####- #####-####-####- #####-000-30-00
Warranty Situation Present?	N
PM Num:	48473

Job Plan:	2954
Job Desc:	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007703

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

s2 7-27-17 Riding inspection due to manpower shortage. No new defects noted in area.

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													217.36



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3007703

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

s2 7-27-17 Riding inspection due to manpower shortage. No new defects noted in area.

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Linthicum To Camden - BWI

[illegible][illegible]

Reason for Inspection _____

7/28/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 7-27-2017 Page 1 of 1

Watchman Lam WO# 3007689

Inspection From Hunt Valley To Lutherville

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.	862400		0			M305	301	Y	N	
2.	848450		0			M307	314	Y	N	
3.					837	S305	322	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items	Comments
1	LRV wheels breaking concrete of Flange way 15'
2	Fouled ballast 3 cribs 4 ties pumping
3	4 loose bolts in the Frog
	Track inspection complete

Were switches in area inspected? YES ☒ NO ☐

Is this a Special Inspection? YES ☐ NO ☒

Reason for Inspection _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

7/28/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Linn Date 7-28-2017 Page 2 of 2

Watchman _____ WO# 3016504

Inspection From North Ave yard To _____

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items	Comments
	NO new defects noted
	in yard
	yard inspection complete

Were switches in area inspected? YES L NO _____

Is this a Special Inspection? YES _____ NO C

Reason for Inspection _____

[Signature]
Track Inspector's Signature

[Signature]
Supervisory Certification

7/31/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 7-28-17 Page 1 of 2

Watchman ham WO# 3066504

Inspection From Cold Spring To Camden yard
Penn

Items	Exception Chain Marker No.		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W.O #
	From	To				Comp.	Defect			
1.					91-3	S305	322	Y	N	
2.					88-3A	S305	301	Y	N	
3.					91-1	S307	301	Y	N	
4.	93+65		1			S305	322	Y	N	
5.					88-4	S304	348	Y	N	
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items	Comments
1	2 Loose bolts in Frog area
2	Rail ends the Frog and connecting running Rails are mismatched 1/8" and have chips missing out of them
3	throw handle bent and needs to be replaced
4	East Frog in diamond has 4 loose bolts in it
5	Micro Fractures in straight switch point

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

7/31/17
Date

7/29



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3012190 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
No new defects noted in area
Trash inspection complete

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading	
CI:					
Mileage Meter:					
Sched Start:		Site:	LTRAIL	Job Plan:	2961
Sched Finish:		Priority:	1	Job Desc:	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
Target Start:	8/2/17	Work Type:	PM	Supervisor:	
Target Finish:	8/2/17	Status:	CLOSE	Lead:	JREAVES3
Actual Start:	7/29/17	Parent:		Owner:	
Actual Finish:	7/29/17	Person Group:	MTA527	Owner Group:	
Report Date:	7/25/17	GL Account:	J05-#####-05270-#####-0901-#####-#####-000-30-00	Service:	
Reported By:	MTACRON	Warranty Situation Present?	N	Service Group:	
Requestor of Work:		PM Num:	48481	Classification:	2732
				Part Failure:	



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3012190 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
No new defects noted in area
Trash inspection complete

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3012190 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
No new defects noted in area
Trash inspection complete

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
20	AREPAIR		GLAM				10		N		08:00	00:00	210.32
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
Total Actual Labor:													420.64



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3012190 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
No new defects noted in area

Trash inspection complete

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Cromwell To Linsticum

[illegible]

COPY

[illegible]

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES _____ NO

Reason for Inspection _____

Track Inspectors Signature

Jimm Beaver
Supervisory Certification

7/31/17
Date

7/30



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3016521

TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
s4 7-30-17 No new defects noted in area.

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/4/17
Target Finish:	8/4/17
Actual Start:	7/30/17
Actual Finish:	7/30/17
Report Date:	7/28/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016521 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
s4 7-30-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		SSELL				10		N		08:00	00:00	212.00
	AREPAIR		ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016521 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
s4 7-30-17 No new defects noted in area.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Inspection From Camden To Linthicum

[illegible][illegible]

Reason for Inspection _____

Janna Reava
Supervisory Certification

7/31/17
Date

